

Michael O. Leavitt

DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple, Suite 1210

Kathleen Clarke **Executive Director**

Governor

Lowell P. Braxton 801-538-7223 (TDD) Division Director

PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax)

INSPECTION REPORT

Partial: XXX Complete	: Exploration:
Inspection Date & Tim	
Date of Last Inspection	

Mine Name: Wildcat Loadout	County: Carbon	Permit Number:	
Permittee and/or Operator's Name: _	Andalex Resources, Inc.	77	
Business Address: P.O. Box 902,	Price, Utah 84501		
Type of Mining Activity: Undergrou	und Surface	Prep. Plant XXX	Other
Company Official(s): Mike Glasso	n		
State Official(s): Bill Malencik	Federal Official(s): None		
Weather Conditions: Temp 80's m	ine had some rain this week		
Existing Acreage: Permitted 100	Disturbed <u>63.7</u> Reg	graded Seeded _	
Status: Active XXX			

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below. 2.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	<u>N/A</u>	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE		\Box	\Box	Ш
2.	SIGNS AND MARKERS	[X]	\Box	[X]	\Box
3.	TOPSOIL	[X]	\Box	[X]	П
4.	HYDROLOGIC BALANCE:				
	a. DIVERSIONS	[X]	\Box	[X]	\Box
	b. SEDIMENT PONDS AND IMPOUNDMENTS	[X]		[X]	П
	c. OTHER SEDIMENT CONTROL MEASURES	[X]	\Box	[X]	П
	d. WATER MONITORING	[X]		[X]	П
	e. EFFLUENT LIMITATIONS	[X]	\Box	[X]	
5.	EXPLOSIVES	П	[X]	\Box	\Box
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[X]	\Box	\Box	
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	П	\Box	\Box	· [_]
8.	NONCOAL WASTE	[X]	Ц	[X]	П
9.	PROTECTION OF FISH, WILDLIFE AND RELATED	\Box	\Box	\Box	П
	ENVIRONMENTAL ISSUES				
10.	SLIDES AND OTHER DAMAGE	\Box	\Box	\Box	\Box
11.	CONTEMPORANEOUS RECLAMATION	\Box	\Box	\Box	П
12.	BACKFILLING AND GRADING	[X]	\Box	\Box	П
13.	REVEGETATION	\Box	\Box	Ц	П
14.	SUBSIDENCE CONTROL	\Box	[X]	Ц	П
15.	CESSATION OF OPERATIONS	П	\Box	П	П
16.	ROADS:				
	a. CONSTRUCTION/MAINTENANCE/SURFACING	[X]	\Box	[X]	П
	b. DRAINAGE CONTROLS	[X]	\Box	П	\Box
17.	OTHER TRANSPORTATION FACILITIES	\Box	\Box	П	\Box
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	\Box	\Box	\Box	\Box
19.	AVS CHECK (4th Quarter- April, May, June)	П	\Box	\Box	\Box
	AIR QUALITY PERMIT	[X]	П	[X]	Ц
	BONDING & INSURANCE	П			П

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: <u>C/007/033</u>

4

DATE OF INSPECTION: <u>07/17/2001</u>

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

GENERAL COMMENTS

The mine area received a storm during the week. The storm caused a maintenance problem on several diversions. The mine had immediately regraded several diversions that needed attention. Observed these diversions and the work was in compliance with the coal rule's.

All temporary impoundments A through F contained runoff. Examining each of the impoundments revealed that none of the ponds discharged. The permanent impoundment was dry and did not receive any runoff.

2. SIGNS AND MARKERS

The ID sign was observed and it contained the required information, address, telephone number, and permit numbers.

The disturbed markers, topsoil markers, and sediment pond markers were all observed and there was not any problems with any of the markers.

3. TOPSOIL

The topsoil piles were observed. There were no resources leaving the area. The berm provides secondary control and sparse vegetation is the primary control.

4A. HYDROLOGIC BALANCE: DIVERSIONS

All ditch designs were observed and meet the coal rules. All the disturbed ditches report to the ponds with the exception of the BTCA area lying south of pond B, which is controlled by straw bales in a BTCA area.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The sediment pond was about 40% of total capacity.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

The BTCA lies south of the loadout, adjacent to sediment pond B, and contiguous to the net wire fence. The straw bales were all replaced this spring. The BTCA area was in good shape.

4D. HYDROLOGIC BALANCE: WATER MONITORING

WCW-1, 2, 3, and 4 had no flow. Effort to sample was made on 06/29/2001. All stations had no flow.

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/007/033

DATE OF INSPECTION: 07/17/2001

4E. HYDROLOGIC BALANCE: EFFLUENT LIMITATIONS

All ponds were dry and did not discharge. The loadout issued a no discharge report for the month of May.

8. NONCOAL WASTE

The area was clear of noncoal waste material.

16A. ROADS: CONSTRUCTION/MAINTENANCE/SURFACING

Roads were maintained. The roads were watered to keep down the fugitive dust.

20. AIR QUALITY PERMIT

Air Quality Permit was updated on 11/01/1999 and provides for five million tons of coal to be processed each year.

Inspector's Signature: Date: July 23, 2001

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

sd

cc: James Fulton, OSM

Mike Glasson, Andalex

Price Field office

O:\007033.WCL\Compliance\2001\p 0717.wpd